

400W MONO/STEREO AMPLIFIER

Universal, robust and compact are the words to describe this amplifier.

Total solder points: 264 Difficulty level: beginner $1 \Box 2 \Box 3 \Box 4 \boxtimes 5 \Box$ advanced



K4005B

ILLUSTRATED ASSEMBLY MANUAL

H4005B-IP-2

Features:

- ☑ Rms output power : 2 x 100W / 4ohm ; 2 x 75W / 8ohm.
- ☑ Rms mono-bridged power : 200W / 80hm.
- ☑ Total music output : 400W.
- ☑ Harmonic distortion : 0.003% at 1KHz.
- ☑ Signal-to-noise ratio : 96dB (A-weighted).
- ☑ Stereo channel separation : 76dB.
- ☑ Damping factor (at 100Hz) : > 2000.

Specifications:

- Input impedance : 22kohm .
- Input sensitivity : 150mV, 300mV or 950mV switchable .
- Supply voltage for 8 ohm : + 35 to 40VDC and 35 to 40VDC / 2.5A.
- Supply voltage for 4 ohm or mono: + 25 to 30VDC and 25 to 30VDC/ 5A
- Dimensions : 350 x 62 x 85mm (13.8" x 2.5" x 3.4").

modifications reserved

1. Assembly (Skipping this can lead to troubles !)

Ok, so we have your attention. These hints will help you to make this project successful. Read them carefully.


1.1 Make sure you have the right tools:

- A good quality soldering iron (25-40W) with a small tip.
- Wipe it often on a wet sponge or cloth, to keep it clean; then apply solder to the tip, to give it a wet look. This is called 'thinning' and will protect the tip, and enables you to make good connections. When solder rolls off the tip, it needs cleaning.
- Thin raisin-core solder. Do not use any flux or grease.
- A diagonal cutter to trim excess wires. To avoid injury when cutting excess leads hold the lead so they cannot fly towards the eyes.
- Needle nose pliers, for bending leads, or to hold components in place.
- Small blade and Phillips screwdrivers. A basic range is fine.

ريَّ For some projects, a basic multi-meter is required, or might be handy

1.2 Assembly Hints :

- \Rightarrow Make sure the skill level matches your experience, to avoid disappointments.
- ⇒ Follow the instructions carefully. Read and understand the entire step before you perform each operation.
- \Rightarrow Perform the assembly in the correct order as stated in this manual
- \Rightarrow Position all parts on the PCB (Printed Circuit Board) as shown on the drawings.
- \Rightarrow Values on the circuit diagram are subject to changes.
- \Rightarrow Values in this assembly guide are correct*
- \Rightarrow Use the check-boxes to mark your progress.
- \Rightarrow Please read the included information on safety and customer service
- ⇒ * Typographical inaccuracies excluded. Always look for possible last minute manual updates, indicated as 'NOTE' on a separate leaflet.



6

0.000

o

1.3 Soldering Hints :

1- Mount the component against the PCB surface and carefully solder the leads

2- Make sure the solder joints are cone-shaped and shiny


3- Trim excess leads as close as possible to the solder joint


REMOVE THEM FROM THE TAPE ONE AT A TIME !


DO NOT BLINDLY FOLLOW THE ORDER OF THE COMPONENTS ONTO THE TAPE. ALWAYS CHECK THEIR VALUE ON THE PARTS LIST!













2. 1/4W INESISIONS				
AND A	R			
□ R1 : 22K □ R3 : 22K □ R3 : 22K □ R4 : 22K □ R5 : 22K □ R6 : 22K □ R6 : 22K □ R8 : 2K2 □ R9 : 1K8 □ R10 : 7K5 □ R11 : 20K	$\begin{array}{l} (2 - 2 - 3 - B) \\ (2 - 2 - 2 - B) \\ (1 - 8 - 2 - B) \\ (1 - 8 - 2 - B) \\ (7 - 5 - 0 - 1 - 1) \\ (2 - 0 - 0 - 2 - 1) \end{array}$			


🗆 R12		47K	(4 - 7 - 3 - B)	
🗆 R13			· /	
🗆 R14		68K	(6 - 8 - 3 - B)	
🛛 R15	:	220K	(2 - 2 - 4 - B)	
🛛 R16	:	1K5	(1 - 5 - 2 - B)	
🗆 R17	:	1K5	(1 - 5 - 2 - B)	
🛛 R18	:	560	(5 - 6 - 1 - B)	
🛛 R19	:	560	(5 - 6 - 1 - B)	
🗆 R20	:	2K7	(2 - 7 - 2 - B)	
🖵 R21	:	2K7	(2 - 7 - 2 - B)	
🗆 R22	:	100K	(1 - 0 - 4 - B)	
🗆 R23	:	470K	(4 - 7 - 4 - B)	
🗆 R24	:	10K	(1 - 0 - 3 - B)	
🛛 R25	:	33	(3 - 3 - 0 - B)	
🖵 R26	:	33	(3 - 3 - 0 - B)	
🗆 R27	:	33	(3 - 3 - 0 - B)	
🗖 R28	-	33	(3 - 3 - 0 - B)	
🛛 R29		390	(3 - 9 - 1 - B)	
🗆 R30		390	(3 - 9 - 1 - B)	
🗆 R31			(3 - 9 - 1 - B)	
🗆 R32	:	390	(3 - 9 - 1 - B)	

Construction

vellemen









18. Power transistors Two transistors are mounted at both ends of the heat sink (for their positions refer to Fig. 3.0). □ T1 & T2 : TIP142 of motorola! □ T3 & T4 · TIP147 of motorolal т1 Т2 0 0 -0 0 тз T4 FIG. 3.0 Bend the connections of each transistor as in Fig. 4.0. FIG. 4.0 TRANSISTOR □ Put them in the correct position on the heat sink and against the P.C.B., mark the place of the transistors. □ Apply a drop of thermally conductive paste to the points where the transistors will be mounted (Fig 5.0). Т1 Τ2 T3 FIG. 5.0 thermally conductive paste Put an insulating mica on the drop of paste.

- Apply a drop of paste on each transistor and put them in the correct position on the heat sink and against the P.C.B. Make sure the correct type of transistor is placed in the correct position (T1...T4).
- □ Fix the transistors well in place by means of the supplied plate and a hexagonal bolt, which is slit into the slot in the heat sink (see Fig. 6.0). Make sure the transistor connections do **NOT TOUCH** the metal plate!



□ Now the transistors may be soldered to the corresponding print pins.








Diagram power supply



13

Diagram







VELLEMAN KIT NV Legen Heirweg 33 9890 Gavere Belgium Europe Info ?: http://www.velleman.be

Modifications and typographical errors reserved © Velleman Kit nv H4005B IP - 2004 - ED2 (rev3)

