Connection diagram of the 0 to 60 hour start/stop timer with suppression of inductive loads.

K6200